

# Monroe

Prompt cleaning is always recommended. Recommended cleaning steps are listed by type of stain. For best results follow cleaning steps in order.

## RECOMMENDED CARE AND CLEANING STEPS

- Step 1: Mild soap and water, then rinse with fresh water and wipe dry with a clean cloth.
- Step 2: Wipe affected area with a soft cloth or soft bristle brush using a non-abrasive cleaner, for example Formula 409 or Fantastik. Rinse with fresh water and wipe dry.
- Step 3: 10% solution of household bleach and water. Rinse with fresh water and wipe dry.
- Step 4: 25% solution of alcohol and water. Rinse with fresh water and wipe dry.
- Step 5: 25% solution of lighter fluid or nail polish remover and water. Rinse with fresh water and wipe dry.

## REGULAR CLEANING AND MAINTENANCE

Clean the soiled area with mild soap and water, then rinse with fresh water and wipe dry with a clean cloth.

## EXAMPLE

Dirt  
Dust  
Grime

## FOOD STAINS / OILS

Wipe affected area with a soft cloth or soft bristle brush using a non-abrasive cleaner, for example Formula 409 or Fantastik. Rinse with fresh water and wipe dry.

Ketchup  
Chocolate  
Coffee  
Tea  
Juice

## HEALTHCARE

Clean the soiled area with a 10% solution of Household Bleach and water. It is important to rinse the cleaned area with fresh water after applying the bleach solution.

Blood  
Urine  
Betadine  
Disinfectant

## DIFFICULT STAINS

Clean the soiled area with 50% solution of Isopropyl Alcohol (Rubbing Alcohol) and water. It is important to rinse the cleaned area with fresh water after applying the alcohol solution.

Eye shadow Mascara  
Lipstick  
Crayon  
Grease  
Mustard

**NOTE: The use of commercial vinyl conditioners and protectants is NOT RECOMMENDED.**

The information in this cleaning guide refers to performance of Resilience in specific tests conducted under laboratory conditions. This information is not a guarantee and does not relieve the user from the responsibility of the proper and safe use of the product and referenced cleaning agents.